


Extreme switching duty



Normal AC induction motor

Operating characteristics

Inching, plugging, reversing

Electrical characteristics:

Switch on: up to $6 \times$ Rated motor current

Switch off: up to $6 \times$ Rated motor current

Utilization category


100 % AC-4

Typical applications:

Printing machines Wire-drawing machines Centrifuges

Special drives on manufacturing and processing machines

Switching conditions for non-motor loads, 3 pole, 4 pole



Operating characteristics

Non inductive and slightly inductive loads

Electrical characteristics:

Switch on: $1 \times$ Rated current

Switch off: $1 \times$ Rated current

Utilization category

100 % AC-1

Typical applications:

Electric heat